



## PMA CROSS REFERENCE CHART

### FAA PMA Sealant Cross Reference Chart

PMA Part Number	Class	PRC/PPG Product	PMA No./ Supplement No.
<a href="#">NSL870</a>	B1/2, B2, B4	P/S 870	PQ4210CE
<a href="#">NSL890RC</a>	A1/2, A2, B1/2, B2, B4	P/S 890	PQ4210CE
<a href="#">NSL1422</a>	A1/2, A2, B1/2, B2	PR-1422	PQ4210CE
<a href="#">NSL1422RC</a>	A1/2, A2, B1/2, B2	PR-1422	PQ4210CE
<a href="#">NSL1428</a>	B1/2, B2	PR-1428	PQ4210CE
<a href="#">NSL1440RC</a>	A1/2, A2, B1/2, B2	PR-1440	PQ4210CE
<a href="#">NSL1750</a>	B1/2, B2	PR-1750	PQ4210CE
<a href="#">NSL1776M</a>	B1/2, B2	PR-1776M	PQ4210CE

### FAA PMA Silicone Cross Reference Chart

PMA Part Number	GE-Momentive/Dow Corning Product	PMA No./Supplement No.
<a href="#">AS106</a>	GE 106, Dow Corning 736	PQ4210CE
<a href="#">AS112</a>	GE 112	PQ4210CE
<a href="#">AS116</a>	GE 116	PQ4210CE
<a href="#">AS118</a>	GE 118	PQ4210CE
<a href="#">AS157</a>	GE 157, Dow Corning 732	PQ4210CE
<a href="#">AS159</a>	GE 159, GE 106, Dow Corning 736	PQ4210CE
<a href="#">AS3145 &amp; AS3145P</a>	GE 162, Dow Corning 3145	PQ4210CE

\* Underlined part names in the digital document are linked to their NSL product pages.