



PMA CROSS REFERENCE CHART

FAA PMA Sealant Cross Reference Chart

PMA Part Number	Class	PRC/PPG Product	PMA No. / Supplement No.
NSL870	B1/2, B2, B4	P/S 870	PQ3886CE/ 28
NSL890RC	A1/2, A2, B1/2, B2, B4	P/S 890	PQ3886CE/ 28
NSL1422	A1/2, A2, B1/2, B2	PR-1422	PQ3886CE/ 18
NSL1422RC	A1/2, A2, B1/2, B2	PR-1422	PQ3886CE/ 28
NSL1428	B1/2, B2	PR-1428	PQ3886CE/ 18
NSL1440RC	A1/2, A2, B1/2, B2	PR-1440	PQ3886CE/ 28
NSL1750	B1/2, B2	PR-1750	PQ3886CE/ 18
NSL1776M	B1/2, B2	PR-1776M	PQ3886CE/ 28

FAA PMA Silicone Cross Reference Chart

PMA Part Number	GE-Momentive / Dow Corning Product	PMA No. / Supplement No.
AS106	GE106, Dow Corning 736	PQ3886CE/ 13
AS112	GE112	PQ3886CE/ 3
AS116	GE116	PQ3886CE/ 3
AS118	GE118	PQ3886CE/ 3
AS157	GE157, Dow Corning 732	PQ3886CE/ 3
AS159	GE159, GE106, Dow Corning 736	PQ3886CE/ 3
AS3145 & AS3145P	GE162, Dow Corning 3145	PQ3886CE/ 3