



PMA CROSS REFERENCE CHART

FAA PMA Sealant Cross Reference Chart

PMA Part Number	Class	PRC/PPG Product	PMA No./ Supplement No.
NSL870	B1/2, B2, B4	P/S 870	PQ4210CE
NSL890RC	A1/2, A2, B1/2, B2, B4	P/S 890	PQ4210CE
NSL1422	A1/2, A2, B1/2, B2	PR-1422	PQ4210CE
NSL1422RC	A1/2, A2, B1/2, B2	PR-1422	PQ4210CE
NSL1428	B1/2, B2	PR-1428	PQ4210CE
NSL1440RC	A1/2, A2, B1/2, B2	PR-1440	PQ4210CE
NSL1750	B1/2, B2	PR-1750	PQ4210CE
NSL1776M	B1/2, B2	PR-1776M	PQ4210CE

FAA PMA Silicone Cross Reference Chart

PMA Part Number	GE-Momentive/Dow Corning Product	PMA No./Supplement No.
AS106	GE 106, Dow Corning 736	PQ4210CE
AS112	GE 112	PQ4210CE
AS116	GE 116	PQ4210CE
AS118	GE 118	PQ4210CE
AS159	GE 159, GE 106, Dow Corning 736	PQ4210CE
AS157	GE 157, Dow Corning 732	PQ4210CE
AS3145 & AS3145P	GE 162, Dow Corning 3145	PQ4210CE